



	
<b>RDM830-100</b>	
	830
	> 100
	5
( $1/e^2$ ),	0,5
	SM
(FWHM),	3
	, 1:50
	210
	$5 \pm 10\%$
( $\lambda$ ), °C	-10~+75
, °C	-30~+85
(diam.xL),	11x40
	35
	1

[www.lascompany.ru](http://www.lascompany.ru)

[info@lascompany.ru](mailto:info@lascompany.ru)

./ : +7(812)448-08-13